

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Last Updated: 10/18/2021 10:07:26 AM

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
	A100S SSCVR 001	Orig	8/23/1996	SERVICING POLICIES FOR SSCVR'S WITH EXPIRED FACTORY WARRANTY		
AFIRS 228S Iridium	ARF SIL005	04	2/5/2018	IRIDIUM SATELLITE DATA UNIT SDU P/N: 228E5733-00, SOFTWARE UPLOAD AND RETURN-TO-SERVICE		228E573 3-00
CICC/4 CICC-4 FA2100	ARF SIL007 CICC4-001	Orig 02	3/16/2018 8/4/2021	FACTORY AND REPAIR STATION MOVE FROM SARASOTA, FLORIDA TO GRAND RAPIDS, MICHIGAN Notification of obsolescence		17TES00 73
	FA2100CVR 001	Orig	3/1/2001	MODEL FA2100CVR UPGRADE FOR A100/A100A INSTALLATIONS		
	L3AP-008	A	5/24/2019	L3AP repair station locations, equipment stock, and part number identification		
QAR200	QAR 002	Orig	11/15/2005	FLASH CARD REPLACEMENT		
	SIL-001	00	5/1/2020	Cleaning and disinfecting guidance.		
7100 SRVIVR2 5	SIL-001-7100	00	10/5/2021	SRVIVR25 CVR/CVDR Greenwich Mean Time (GMT) date and time mismatch.		
ADLP CATS FA2100 FA2300 PI/1 PI/2 RDI ROC/7 ROSE	SIL-001-L3AP	00	5/27/2021	If synchronized CVR audio data is required, the .CVR format must be downloaded from the recorder. The .CVR format will produce synchronized audio between all channels		
7100 FA2100 FA5000 RDI SRVIVR2 5	SIL-001-RDI	00	10/6/2020	Introduction of new tablet-based Recorder Data Interface (RDI)		
TSC-1000	SIL-001-TSC-1000	00	10/28/2020	Touch Screen Controller (TSC) Operation		9200-44 000-010 1
TSC-1000	SIL-002-TSC-1000	00	6/16/2021	Touch Screen Controller (TSC) Packaging		9200-44 000-010 1
fa2100 fa2300 fa5000 QAR	SIL-003	00	5/25/2021	To provide customers a means of identifying legacy Recorder product part numbers		
	SL-1	F	5/16/2018	Provide general repair instructions for circuit card assemblies.		

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
ADI-330 ADI-331 ADI-332 ADI-333 ADI-334 ADI-335 ADI-336 ADI-350 ADI-363, AI-330 AI-350 AI-360 AI-803() AI-804() AI-903 AI-904 DG-110 DG-710 DN-101 DN-104 DN-501 DN-600 RG-225 RG-227 VG-204 VG-206 VG-208 VG-301 VN-202	SL-10	T	10/8/2018	To provide all service facilities and aircraft operators information concerning gyro handling, storage, packaging, and shipping.		
SA-142() SA-200() SA-400() SA-500	SL-102	Orig	11/4/1987	To provide information for the proper method of adjusting the brush block to armature contact and general burn-in requirements.		501-106 7-() 501-111 2-() 501-121 2-()
SP-101()	SL-103	1	2/15/1987	To extend compliance requirement of subject service bulletin.		501-113 3-()
PS-835()	SL-105	A	4/5/1988	To provide a PS-835 Power Supply self-test procedure for units installed in Cessna Citation Aircraft.		501-122 8-()
PS-823() PS-835()	SL-109	A	8/7/2000	To inform users and service centers the merits of using BFG inspected of cells.		
PS-800() PS-801 PS-823()	SL-11	B	6/11/1986	To provide Emergency Power Supply use information. (Contact Learjet for parts and service).		501-104 6-() 501-107 5-()
JT-39A	SL-110	Orig	5/8/1989	To inform users and service centers of possible incorrect components.		510-102 5-01

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
4-8020 VG-204 VG-206 VG-208	SL-111	Orig	12/1/1989	To provide gyro service centers with information regarding allowed use of DG-106 alternate solvent for performing gyro leak check.		
General	SL-112	Orig	2/14/1990	To maintain BFG policy that certain assemblies and subassemblies are not field reparable.		
General	SL-114	A	10/21/1991	To provide BFG service centers with information concerning the substitution of RCR07XXX resistors with RCR07XXXJR resistors.		
CA-530H CA-530J CA-530K	SL-116	A	7/2/1993	To provide customers with bench level test procedures for the subject computer amplifiers pending a component maintenance manual generation.		501-155 3-01 501-155 3-02 501-155 3-03
DG-710A DG-710C	SL-118	Orig	9/2/1993	To provide authorized service centers and users of these products the minimum configuration requirements relative to modifications incorporated into the directional gyro.		501-151 5-01 501-151 5-02
ETC-404E	SL-119	Orig	9/20/1993	To provide all current repair centers for Model ETC-404E Engine Temperature Cycle Counter with the procedures required to assemble U17 (P/N 545-1016-01) Programmed Microcircuit to A1 Computer Circuit Card Assembly (CCA) (P/N 542-1728-05).		501-150 6-05
AI-804() AI-904()	SL-12	E	4/23/2010	To provide Attitude Indicator operation information.		
PS-834() PS-834A PS-834B	SL-120	F	11/30/2009	To provide a procedure which will permit charging and testing of the PS-834 Emergency Power Supply using a locally generated test set-up, to determine the integrity of the unit prior to installation in an aircraft, or to satisfy the annual charge/discharge		501-168 2-() 501-168 2-01 501-168 2-02
3S2060D M169A1 3S2060D M169A3	SL-121	B	5/5/2009	To provide information necessary to repair units and improve unit reliability.		3S2060D M169A1 3S2060D M169A3
DG-710A DG-710C	SL-133	Orig	4/8/1997	Current Authorized Configuration For Circuit Card Assemblies and Software.		501-151 5-01 501-151 5-02
WX-SM	SL-137	A	6/11/1997	Skin mapping		78-8060- 5869-5
NY156 Antenna	SL-139	Orig	9/17/1997	To provide information on the limitations for warranty consideration.		800-102 54-002 805-100 03-001
TRC791	SL-140	Orig	9/17/1997	To provide information on the limitations for warranty consideration.		
	SL-141	N	3/31/2016	To provide customers a list of technical manuals available for sale by Aviation Products.		

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
	SL-144	A	8/31/1998	Listings of product model numbers and related ownership, design authority, and service responsibilities.		
VG-208()	SL-152	Orig	1/21/1998	Provide information on how to replace RCR resistor with an RWR sized resistor.		501-112 1-01 501-120 9-01 501-121 0-01 501-168 7-01
ADI-() AI-()	SL-153	A	5/16/2018	Elimination of Internal Moisture in Attitude Indicators.		
LNS6000	SL-154	Orig	4/23/1998	To provide proper configuration setup procedures and replacement of GPS antenna.		805-100 08-()
	SL-156	B	2/27/2019	Define the L3 Aviation Products Exchange/Overhaul Program and acceptable/unacceptable exchange core to the field.		
ADI-() AI-() DG-() VG-()	SL-159	Orig	3/8/1999	Establishment of policy requiring use of clean room environment during disassembly, repair, and assembly for all AI/ADI/VG and DG products, except AIM products.		
SI-1250 SI-1500 SI-2500 SI-3000 SI-3003	SL-16	B	9/4/1987	To provide information on periodic replacement of SI-2500() and SI-3000() input capacitors.		
DB-380A	SL-160	Orig	5/13/1999	Establishment of new torque requirement when attaching Capstan to Servo Actuator.		501-177 1-01
GH-3000 A GH-3000 B GH-3000 C GH-3000 D GH-3000 E GH-3000 F GH-3000 G GH-3000 H	SL-161	Orig	6/4/1999	To establish product knowledge and availability of new GH-3000 with Release 2.0 Software.		
AI-803()	SL-162	Orig	6/10/1999	To establish authorization to remove lead seal and replace with safety wire.		
ADI ADI-33()	SL-163	A	12/14/2004	To provide flight personnel with general information concerning operation of AI/ADI-33 (X) Attitude Indicators.		

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
GH-3000()	SL-165	B	11/15/2010	Electronic Standby Indicator System (ESIS) Attitude Operation		501-174 1-() 501-174 1-()01 501-174 1-()02 501-174 1-()03
GH-3000()	SL-169	E	5/15/2002	To advise customers of differences among GH-3000 part numbers, and upgrade policies and procedures.		501-174 1-()
SI-2500A SI-2500B	SL-17	Orig	9/20/1977	To provide information concerning avionics changes or new operational procedures.		501-112 8-01 501-112 8-02
501-1719-01 PS-850 PS-855	SL-170	K	7/23/2014	PS-850/PS-855 Battery Inspection, Storage and Maintenance Procedures.		501-171 2-() 501-171 2-01 501-171 2-02 501-171 2-03 501-171 2-04 501-171 9-() 501-171 9-01 501-171 9-02
AI-804()	SL-172	Orig	4/12/2001	To inform Authorized Repair Facilities of correct manual use when repairing the AI-804 () Attitude Indicator.		
VG-208B	SL-173	Orig	5/2/2001	To authorize replacement of Bendix Identification Plate and Modification Decal for service centers with access to TP-260.		501-120 9-01
ADI-() AI-() DG-710 RG-225 RG-227 VG-204() VG-206() VG-208()	SL-174	A	4/3/2015	To provide Avionics Systems, Inc service centers and maintenance personnel with storage information for gyro products. [Replaces SL-113, SL-131, SL-168, SA-89].		
4-8020 ADI-() AI-() BC-()	SL-175	D	7/18/2016	Cross-reference of Avation Products chemical part numbers to vendor and vendor numbers.		

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
CA-() DAC-() DB-() DG-() DGS-() DN-() ETC-() ETM-() FC-() FU-() GH-() GL-() HI-() IA-() JT-() PB-() PC-() PL-() PM-() PS-() RAI-() RG-() SA-() SC-() SI-() SP-() SPS-() VG-() WHC-() YD-()						
ADC-3000 ADC-3001	SL-176	H	9/23/2010	Provide factory generated tolerance settings of altitude accuracy for certified repair stations.		501-1797-() 501-1841-() 501-1881-() 501-1890-()
501-1741-() ADC-3000() GH-3000()	SL-177	C	5/13/2004	To inform flight line technicians about air data anomalies they may observe on the GH-3000 Electronic Standby Instrument System display and instructions to correct the air data invalidities.		501-1741-() 501-1797-()
GH-3000()	SL-179	A	4/28/2004	To provide information concerning fan failures during power ON self-testing.		501-1741-()

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
GH-3100()						501-1860-()
SI-2500A SI-2500B	SL-18	A	7/29/1980	To provide SI-2500 modification status (circa 1980).		501-1128-01 501-1128-02
VG-204A B VG-204Y	SL-180	Orig	4/17/2003	To advise authorized service centers on repair of Frame Circuit Card Assemblies.		501-1255-01 501-1453-01
HSI-3000	SL-181	Orig	4/16/2003	Update indicators with 1.C3 software to 2.0 software.		501-1847-01
MAG-3000	SL-182	Orig	4/29/2004	Exposure of the magnetometer to magnetic fields.		501-1826-01 501-1826-02
MAG-3000	SL-183	Orig	11/14/2003	Rejections in field due to visual inspections and mishandling of product.		501-1826-01
AI-903()	SL-184	Orig	12/5/2003	Proper Operation of Caging Knob		
ADC-3000	SL-185	Orig	1/20/2004	Inform customers of the Cessna Citation Bravo Series Aircraft of Airdata problem.		501-1741-()
GH-3000()						
GH-3100	SL-186	G	4/9/2015	The GH-3100 Electronic Standby Indicator is subject to requirements of FAA document 14 CFR FAR Part 91.411 every 2 years		501-1860-()
GH-3000() GH-3004() GH-3100()	SL-189	B	12/7/2004	1. Import / Export control issues. 2. Modification status of models GH-3000, GH-3004, and GH-3100.		501-1741-() 501-1859-() 501-1860-()
ADC-3000	SL-190	Orig	9/15/2004	Missing electro magnetic intererence (EMI) filter seal.		501-1797-() 501-1881-() 501-1890-()
SI-1500L	SL-202	Orig	11/9/2004	Mislabeled Identification Plate.		501-1666-02
TAWS8100	SL-203	A	1/11/2005	Notify dealers that the TAWS8100 requires an extra pin on the serial cable (pin 7) when using the service menu via laptop.		805-18650-001
TAWS8100	SL-205	Orig	12/8/2004	Remove caution and limitation of installing a TAWS8100 on an aircraft equipped with SATCOM.		805-18650-001
NY156 NY164	SL-206	B	5/16/2018	Remove tape holding O-RING in place before installing antenna on aircraft.		805-10003-001

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
ADI-333B	SL-208	A	5/24/2006	To provide instructions for replacing caution label.		805-108 90-001 501-165 7-02
PB-1002A PB-1003A PB-1004A PL-100A PL-103A SI-1000 SI-1250 SI-1500 SI-2500 SI-3000 SI-3003	SL-21	F	9/21/1987	To provide information when installing BFG Static Inverters, Phase Lock Boxes and Parallel Systems in various aircraft.		
JT-147A	SL-215	A	10/4/2006	No periodic calibration or maintenance for the JT-147A Calibration Test Set is required.		570-855 2-01
ADI-333 ADI-333B	SL-217	A	1/2/2007	To provide a means of monitoring temperature of units in the field and to provide guidance of the location of the temperature tag.		501-165 7-02
RGC-350	SL220	A	4/26/2007	Permission to use STC		805-124 00-() 805-124 00-001 805-124 00-002
LANDMAR K TAWS 8000 TAWS 8000	SL-221	A	7/19/2007	Permission to use STC		805-180 00-001
LANDMAR K TAWS-81 00 TAWS-81 00	SL-222	A	4/26/2007	Permission to use STC		805-186 50-001
MAG-300 0	SL-225	A	5/15/2007	To provide customers with a procedure to check and calibrate the MAG-3000 magnetometer.		501-182 6-() 501-182 6-01 501-182 6-02 501-182 6-03
GH-3000	SL-226	A	5/15/2007	To provide product upgrade information due to product obsolescence		501-174 1-01

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
						501-174 1-0102 501-174 1-0103 501-174 1-02 501-174 1-0202 501-174 1-0203 501-174 1-03 501-174 1-0302 501-174 1-0303 501-174 1-04 501-174 1-0402 501-174 1-0403 501-174 1-05 501-174 1-0502 501-174 1-0503 501-174 1-06 501-174 1-0602 501-174 1-0603 501-174 1-07 501-174 1-0702 501-174 1-0703 501-174 1-08 501-174 1-0802 501-174 1-0803
A-100	SL-228	A	7/21/2007	Permission to use STC		9200-18 000-()

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
HI-601D	SL-288	A	7/17/2013	Corrections to Manual		9200-18000-01
TAWS 8000 TAWS 8100	SL-230	A	1/23/2008	Incorrect Elevation Reported for Black Rock Mountain In Canada		501-1652-01 805-18000-001 805-18650-001
SA-341D SA-341E SA-360D SA-380A SA-380C SA-380D SA-380E SA-600D	SL-231	A	2/25/2008	Component Reliability		501-1259-04 501-1478-04 501-1478-05 501-1684-04 501-1770-01 501-1770-03 501-1770-04 501-1770-05
A-100	SL-232	A	4/9/2008	PMA APPROVAL LIST FOR A-100 IRIS		9200-18000-01
	SL-234	B	10/15/2009	Part Number Clarification		
DAC-2000 DC-2001() general	SL-24	Orig	4/24/1978	To provide information on replacement of fuse with bus wire to prevent loss of +28 Vdc due to inadvertent blowing of fuse on DC-2001() Digital Computers containing Power Supply Assembly PN 502-1105-01.		
	SL-240	B	11/21/2011	To inform customers of discontinued support of products owned by Avionics Systems.		
ADC-3000 ADC-4000	SL-243	B	1/9/2018	Replacement of ADC-3000 with ADC-4000		501-1797-() 9200-3000-()
GH-3100	SL-244	B	2/17/2010	Replacement of GH-3100 with SW1.3 with SW 3.X		501-1860-XXX1 501-1860-XXX3
GH-3100	SL-245	A	6/30/2009	GH-3100 YAW Error Correction		501-1860-XXX1
SA-340A SA-341B	SL-246	AT	10/7/2021	Component Replacement List		3S2060D C168A2A

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Aviation Products
L3 Technologies
5353 52nd St. SE
Grand Rapids, MI 49512

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
SA-341C						501-147 8-02 501-147 8-03
GH-3000	SL-251	A	12/3/2009	Supplemental Operation Instructions		501-174 1-3103
TRC-791 TRC-791A	SL-253	B	10/14/2015	Collision Avoidance- Interference Check		805-100 01-001 805-100 01-002 805-100 01-003 805-100 01-004 805-100 01-005 805-100 01-006 805-100 01-021 805-100 01-022 805-100 01-023 805-100 01-024 805-100 01-025 805-100 01-026
ESI-1000 ESI-2000 SA02738 CH	SL-254	E	2/5/2013	ESI-1000/2000 AML STC		9200-32 000-010 1 9200-32 000-020 1 9200-32 100-010 1 9200-32 100-020 1 9200-32 500-001 1

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Aviation Products
L3 Technologies
5353 52nd St. SE
Grand Rapids, MI 49512

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
						9200-32 500-002 1
ADC-4000	SL-255	A	12/22/2015	ADC-4000 Satus Indicator		9200-30 000
MAG-3000	SL-256	A	2/15/2010	MAG-3000 Interchangeability		501-182 6-01 501-182 6-03 501-182 6-04
DCM-3100	SL-259	A	7/12/2010	The DCM-3100 may not be recognized by the GH-310 Electronic Standby Indicator at startup.		501-187 0(-)
	SL-261	F	4/5/2021	Shipping Instructions for International Customers		
DCM-3100	SL-262	A	11/24/2010	The customer (IS&S) requested a change to the -143 configuration data on their Detachable Configuration Module		501-187 0-143
PS-835	SL-264	E	1/26/2017	PS-835 Battery Replacement		501-122 8(-)
i-linc i-linc Chartview i-linc Radar	SL-265	A	3/11/2011	Discontinued Support for i-linc MFD		9200-19 000- 9200-19 020- 9200-19 050- 9200-19 070-
CD-605	SL-266	A	3/21/2011	Recommended Alternate Display Options		805-100 07-005 805-100 07-006 805-100 07-007 805-100 07-008
DG-710B	SL-267	A	6/7/2011	Provide customers with a Go-No-Go Test Procedure		501-165 3-01
ESI-2000	SL-268	A	6/7/2011	To provide information on the installation of the ESI-2000 (P/N 9200-32500-0121) on a Piper Cheyenne II, Type Certificate Data Sheet (TCDS): A8EA		9200-32 500-012 1
PS-834 PS-835 PS-850 PS-855	SL-269	D	5/11/2017	To provide service facilities with shelf life information for sealed lead batteries.		501-122 8(-) 501-168 2(-) 501-171 2(-)

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Aviation Products
L3 Technologies
5353 52nd St. SE
Grand Rapids, MI 49512

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
SI-1250A SI-2500 SI-3000	SL-27	Orig	9/19/1978	To provide information on repair of Static Inverter malfunctions due to excessive moisture using improved moisture proofing compound.		501-171 9()
PS-823	SL-270	C	10/6/2015	To provide service facilities with shelf life information for NiCad batteries		501-107 5-()
ESI-1000	SL-272	B	9/20/2011	MAG Install Softwre Update 1.05		9200-32 100-100 1
	SL-273	A	9/28/2011	ESI-1000 Corrected Vmo Table Definition data		
VG-204 VG-206 VG-208 VG-401	SL-274	A	1/4/2012	To provide offical approval for the use of equivalent test equipment to test and validate the functionality of vertical gyros manufactured by L-3 Avionics Systems.		
VG-204 F, G, Z	SL-275	A	1/26/2012	To provide official approval for the discontinuation of the need to perform reliability tests that may be called out in maintenanc manuals for products listed in the Effectivity paragraph		
	SL-276	A	1/23/2012	To provide users of TP-508 information on corrections to the Illustrated part list		502-101 5-01, 02 502-102 5-04 502-104 4-01, 02 502-115 3-04, 07 502-115 4-07 502-117 7-01, 04, 07, 08, 11, 12, 13, 15 502-124 1-02 502-125 3-01 502-137 8-01, 04, 06 502-144 9-01 502-149 0-01
ESI-1000 ESI-2000	SL-277	A	8/21/2013	Trilogy Congiuration Tool		9200-32 100-010 1

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Aviation Products
L3 Technologies
5353 52nd St. SE
Grand Rapids, MI 49512

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
						9200-32 100-020 1 9200-32 100-100 1 9200-32 500 9200-32 500-001 1 9200-32 500-002 1 9200-32 500-003 1 9200-32 500-004 1 9200-32 500-005 1 9200-32 500-006 1 9200-32 500-007 1 9200-32 500-008 1 9200-32 500-012 1
FC-110 FC-200 FC-530 FC-535 FC-550	SL-280	D	9/6/2018	Autopilot product line sold to Butler Avionics		
501-1197 -32 AI-804CJ	SL-281	A	10/18/2012	TP-218 Manual Corrections		
GH-3100	SL-283	A	1/29/2013	Changes Implemented with 4.0 Software		501-186 0-0102
ESI-2000	SL-286	C	4/1/2016	Annual battery maintenance		9200-32 500

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Aviation Products
L3 Technologies
5353 52nd St. SE
Grand Rapids, MI 49512

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
HSI-3000	SL-287	A	6/20/2013	Fault Code Identification		9200-32501 501-1847-04 501-1847-05
HSI-3000	SL-289	A	8/19/2013	Error code 32 & 38		501-1847-04 501-1847-05
CA-2001A/G CD-2001A/B DAC-2000	SL-29	Orig	1/9/1980	To provide information concerning the installation changes necessary for installing CDU with tactile keyboard.		501-1172-01 501-1172-02
MAG-3000 MAG-3100	SL-291	B	9/24/2013	MAG-3000 Extreme Temperature Fault		501-1826 501-1826-01 501-1826-02 501-1826-03 501-1826-04 501-1826-05 501-1826-06 501-1826-07 9200-21200
	SL-293	E	11/28/2017	Spare Piece Part Sales		
SA-400A	SL-294	D	9/11/2018	SA-400A sold to Butler Avionics		501-1212-01
CA-400 PC-500	SL-298	B	9/11/2018	Product sold to Butler Avionics		501-1211-() 501-1288-()
NGT-9000 NGT-9000+	SL-300	B	3/15/2018	End User License Agreement		9029000-20000 9029000-40000

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Aviation Products
L3 Technologies
5353 52nd St. SE
Grand Rapids, MI 49512

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
NGT-9000 D						
NGT-9000 R						
NGT-2000 NGT-2500	SL-301	A	7/23/2015	Mode A Error Detection Handling with GTX327/330		9022500 -10000
NGT-9000 NGT-9000 R	SL-303	B	3/15/2018	Coax Cable Availability		9029000 9029000 -20000 9029000 -40000
NGT-9000 NGT-9000 D+ NGT-9000 RD+	SL-304	C	3/15/2018	Approval of deviations to the Lynx NGT-9000.		9029000 -20000 9029000 -40000
ESI-500	SL-305	A	12/17/2015	To Prevent damage to MicroSD Card		9200-15 000-010 1
NGT-9000 NGT-9000 + NGT-9000 D NGT-9000 D+	SL-306	D	3/15/2018			9029000 -20000
	SL-307	A	2/29/2016	Maintenance Manual Revision Packets		
NGT-9000	SL-308	B	3/15/2018	Mode S Extended Squitter Transponder Audio Noise Interference		9029000 9029000 -20000 9029000 -40000
ESI-500	SL-309	B	3/29/2018			9200-15 000-010 1
NGT NGT-1000 NGT-2000 NGT-2500 NGT-9000 NGT-9000 + NGT-9000 D NGT-9000 D+	SL-310	B	3/15/2018	Installation Guidance		9021000 9021000 -10000 9022500 9022500 -10000 9022500 -20000 9029000 9029000 -20000

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Aviation Products
L3 Technologies
5353 52nd St. SE
Grand Rapids, MI 49512

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
NGT-9000 R NGT-9000 R+ NGT-9000 RD NGT-9000 RD+						9029000 -40000
PS-823 PS-834 PS-835 PS-850 PS-855	SL-311	B	1/9/2017	Manual Subscription Service Policy		501-107 5 501-122 8 501-168 2 501-171 2 501-171 9
NGT-1000 NGT-2000 NGT-2500 NGT-9000 PIM-9000	SL-313	B	2/16/2017	Compatiblity with ForeFlight App		9021000 -10000 9022500 -10000 9022500 -20000 9029000 -20000 9029000 -40000 9230-17 005-01
L-3 AS	SL-315	B	12/9/2016	Not for distribution		
ESI-500	SL-316	A	12/15/2016			9200-15 000-010 1
NGT-9000 NGT-9000 R	SL-317	B	3/15/2018	68DC; 71DC; & 72DC Database Subscription		
NGT-9000	SL-318	B	3/15/2018	RF Suppression Bus		9029000 -20000
NGT-1000 NGT-2000 NGT-2500 NGT-9000 NGT-9000 R	SL-319	B	3/15/2018	GPS Antenna Approval		9021000 -10000 9022500 -10000 9022500 -20000

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Aviation Products
L3 Technologies
5353 52nd St. SE
Grand Rapids, MI 49512

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
						9029000 -20000 9029000 -40000
NGT-2500	SL-321	A	2/1/2017	Same Bearing Traffic Anomaly		9022500 -10000 9022500 -20000
PS-835 PS-835A PS-835B PS-835C PS-835D PS-835E PS-835F PS-835G	SL-322	A	1/26/2017	PS-835 Battery Replacement Policy		501-122 8 501-122 8-01 501-122 8-02 501-122 8-03 501-122 8-04 501-122 8-05 501-122 8-06 501-122 8-07
ESI-500	SL-323	A	2/28/2017	Setting The Real Time Clock		9200-15 000-010 1
GH GH3000 GH-3000 GH3100 GH-3100	SL-324	A	4/5/2017	End of Production Notice		501-174 1 501-186 0
NGT-1000 NGT-2000 NGT-2500 NGT-9000 NGT-9000 R	SL-326	C	3/15/2018	Degraded GPS Satellite Accuracy Calculations		9021000 -10000 9022500 -10000 9022500 -20000 9029000 -20000 9029000 -40000
ESI-1000 ESI-2000	SL-327	B	7/27/2017			9200-32 000 9200-32 100

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Aviation Products
L3 Technologies
5353 52nd St. SE
Grand Rapids, MI 49512

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
ESI-500	SL-329	A	1/11/2018	ESI-500 Battery Calibration		9200-32500 9200-15000-0101
VG-204() VG-206() VG-208()	SL-33	A	8/28/2000	To provide information on incorporation of Mod No. 20 which reduces pitch Synchro noise		
IN-602 IN-602+	SL-330	B	10/2/2018	Replacement Information for the IN-602		805C0620 9200-35500
PS-823	SL-331	A	3/14/2018	PS-823 Battery Replacement Policy		501-1075 501-1075-01 501-1075-02 501-1075-03 501-1075-04 501-1075-05 501-1075-06 501-1075-08 501-1075-09 501-1075-10 501-1075-11 501-1075-12 501-1075-13 501-1075-14 501-1075-15 501-1075-16
GH-3002 A	SL-333	C	3/28/2019	End of Manufacturing Notice		501-1852-0101

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Aviation Products
L3 Technologies
5353 52nd St. SE
Grand Rapids, MI 49512

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
SIM-3000 SIM-3100	SL-334	A	8/14/2018	End of Production Notice		501-185 2-0103 501-185 2-0203 504-196 6-01 501-182 7 501-189 1 501-190 3
general	SL-335	A	10/23/2019	To provide customers with instructions for Return Materials Authorization (RMA).		
CP-2500 NGT-1000 NGT-2000 NGT-2500 NGT-9000 NGT-9000 R	SL-336	A	9/4/2018	Lynx Publication Transfer to ACSS		9022500 -10000 9022500 -20000 9029000 -20000 9029000 -40000 9021000 -10000 9080-17 250-01 9080-17 250-02 9080-17 250-12
PS-834	SL-337	B	3/28/2019	End of Manufacturing Notice		501-168 2-01 501-168 2-02
ADC-310 0	SL-338	A	11/12/2018	End of Manufacturing Life		501-184 1-
TAWS810 0	SL-342	A	4/18/2019	GPS WAAS 1201 Sensor Issue		805-186 50-001
	SL-344	A	7/29/2019	To inform customers that L3 Aviation Products will no longer be providing hard copies of product Pilot's Guides.		
ESI-500	SL-345	A	8/1/2019	Synthetic Vision Obstacles Causing Unit Restart		9200-15 000-010 1
VG-204() VG-206() VG-208()	SL-35	B	9/13/2000	To clarify operating procedures and erection indications.		

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Aviation Products
L3 Technologies
5353 52nd St. SE
Grand Rapids, MI 49512

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
HI-601	SL-350	A	12/17/2019	End of Manufacturing Notice		501-153 7-01 501-165 2-01
DG-710	SL-351	A	12/17/2019	End of Manufacturing Notice		501-165 3-01
TSC-1000	SL-352	C	6/16/2021	Screen Discolor at Power Up		9200-44 000-010 1
GH-3001	SL-353	A	2/4/2020	Discontinued Literature Package Distribution		
	SL-354	A	2/12/2020	End of Production Notice		501-185 1-
DAC-2000 DAC-7000 DC-2001 DC-7001	SL-36	C	1/8/1981	To provide RNAV System operation that alleviates problems outlined in ALERT Service Bulletins.		
DAC-2000 DAC-7000 DC-2001 DC-7001	SL-37	Orig	6/15/1980	To comply with the final requirements necessary for cancellation of RNAV ALERT Service Bulletins.		
DAC-2000 RC-2001	SL-38	SL-3	9/18/1980	To provide information concerning Continuity checks between the RC-2001 relay mating connector and other RC-2001 Aircraft components.		
	SL-39	A	7/15/1981	To inform BFG product users of suitable replacement parts for hard to procure zener diodes, 1N471A and 1N474.		
PS-800 PS-801	SL-4	A	2/22/1972	To provide information on PS-800/PS-801 battery maintenance. (Contact Learjet for parts and service).		
SL-43 SL-43B	SL-43	B	8/22/2003	To inform customers of web site location of Avionics Systems Service Directives.		
VG-204V	SL-44	A	4/10/1985	To inform customers of the method of correcting VG-204V actuator "buzz or hum" in roll axis.		
CA-200 FC-200 MT-101() SP-101	SL-45	Orig	6/1/1981	To inform customers of potential problems with 2N5822 CA-200 and 2N5195 transistors.		
PS-823() PS-835()	SL-48	A	7/23/2001	To provide information on replacement of PS-823 with PS-835 and SI-100 Static Inverter.		501-107 5-() 501-122 8-()
	SL-49	F	5/16/2018	To provide BFG customers with information concerning the latest moisture/fungus proofing materials/methods being used.		

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Aviation Products
L3 Technologies
5353 52nd St. SE
Grand Rapids, MI 49512

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
PS-823()	SL-5	B	4/15/1983	To provide information on PS-823 battery cell test & maintenance.		501-1075-()
DAC-7000 DC-7001D	SL-50	B	3/3/1982	To improve DeHavilland-7 RNAV operations.		
DAC-2000 DAC-7000 DC-2001 DC-7001	SL-52	Orig	1/18/1982	To eliminate reading the RMI in Test Stages 2 and 3 of RNAV Self Test.		
AI-904	SL-54	B	3/4/1991	To provide gyro overhaul service centers with information regarding updated procedures for model AI-904 Attitude Indicator rotor housing assembly overhaul and repair.		
	SL-57	B	2/2/1984	To prevent possible damage to static sensitive devices.		
FC-110 FC-200 FC-550	SL-58	Orig	7/14/1982	To refrest operators on the fnction and indication of the force meters used on autopilots and raw dampers.		
PS-835()	SL-59	A	8/14/1982	To inform Learjet operators of FAA requirements for use of PS-835() Emergency Power Supplies.		501-1228-()
PS-835	SL-61		10/14/1982	Replaced by SL-84A.		
PS-823 PS-834 PS-835 PS-850 PS-855	SL-64	E	8/19/2010	To inform customers of the effects of battery out gassing.		
	SL-67	CXL	7/26/2005			
SC-841A	SL-69	Orig	5/20/1983	To provide information allowing wider tolerance at No Load, and Low Input Voltage.		
JT-5 PS-800 PS-823	SL-7	Orig	1/2/1973	To provide PS-800 manual correction, JT-5 manual correction, PS-823 manual modification clarification, installation of inductor to reduce effects on PS-823 when keying high capacitance radio and information on gyro handling.		
SI-1250A SI-1500A SI-2500A SI-2500B SI-2500B/P	SL-72	Orig	8/12/1983	To provide power efficiency limits for repaired static inverters.		501-1128-01 501-1148-01 501-1148-02 501-1235-01 501-1249-01
VG-204Z	SL-74	Orig	2/20/1984	To provide information on testing for uniform polarity of wheel magnets.		501-1224-02
	SL-75		3/16/1984	To inform customers of replacement for transistors no longer qualified.		

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Aviation Products
L3 Technologies
5353 52nd St. SE
Grand Rapids, MI 49512

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
AI-804()	SL-77	Orig	5/1/1984	To provide information regarding updated procedures for Model AI-804 Attitude Indicator rotor housing assembly overhaul and repair.		
SI-3000	SL-78	Orig	3/16/1984	To inform customers of applicability of Mods 1, 2, 3 and 4.		
PS-823	SL-79	Orig	5/15/1984	To eliminate vertical freedom of "short" cells in battery packs.		501-107 5-()
PS-823 PS-823A PS823A/T PS-823B PS-823B/ T PS-823C PS-823C/ T PS-823D PS-823D/ T PS-823E PS-823E/ T PS-823F PS-823F/ T PS-823G PS-823G/ T PS-823H PS-823H/ T	SL-8	U	6/23/2011	To provide PS-823 battery pack charging and test information as it appears in Component Maint. Manual TP-202.		501-107 5-() 501-107 5-01 501-107 5-02 501-107 5-03 501-107 5-04 501-107 5-05 501-107 5-06 501-107 5-07 501-107 5-08 501-107 5-09 501-107 5-10 501-107 5-11 501-107 5-12 501-107 5-13 501-107 5-14 501-107 5-15 501-107 5-16
PS-835 PS-835A PS-835B PS-835C PS-835D PS-835E PS-835F PS-835G	SL-80	AD	4/11/2018	PS-835 Battery inspection and maintenance procedures.		501-122 8-() 501-122 8-01 501-122 8-02 501-122 8-03

Service Letter Index

Last Updated: 10/18/2021 10:07:26 AM

Aviation Products
L3 Technologies
5353 52nd St. SE
Grand Rapids, MI 49512

Model Number	Publication Number	Revision Level	Revision Date	Manual Description	Product Description	Part Number
						501-122 8-04 501-122 8-05 501-122 8-06 501-122 8-07
PS-823 PS-835	SL-84	C	2/24/2011	To disseminate battery cell/pack availability/non-availability. (Supersedes SL-61)		
PS-835	SL-85	Orig	12/14/1984	To disseminate information about cell tie down straps.		
VG-204() VG-206() VG-208()	SL-86	Orig	1/28/1985	To disseminate information on mod kit/service bulletin applicability for installing a more reliable stator.		
SI-1000C	SL-90	Orig	8/9/1985	To provide information concerning failure of power transistors during short circuit conditions.		
SI-1000 SI-1250 SI-1500 SI-2500 SI-3000	SL-91	Orig	8/19/1985	To disseminate information concerning the selection of the proper transistors when replacement of the output transistors is necessary.		
SI-1250A	SL-92	Orig	11/13/1985	To remove unnecessary modification number from modification plate.		501-123 5-01
VG-204() VG-206() VG-208()	SL-93	Orig	4/22/1986	To provide precautions for handling electrolytic switches.		
SI-3000()	SL-94	Orig	6/10/1986	To provide clarification of transistor sets installed.		
SA-142() SA-200 SA-400() SA-500()	SL-95	1	10/25/1988	To provide information concerning the inspection and overhaul intervals for servo actuators.		
SI-3000A SI-3000B	SL-96	Orig	11/11/1986	To delete inappropriate test data and clarify questionable test procedures.		
SA-350A	SL-97	B	10/15/1987	Cancellation of periodic scheduled maintenance for the SA-350A Servo Actuator.		
SI-3003B SI-3003C	SL-98	A	3/23/1993	To provide information concerning the intake of inverter exhaust air, causing ambient air heat build-up and potential inverter failure.		
SA-151() SA-200() SA-350() SA-400() SA-401() SA-460() SA-500()	SL-99	A	2/16/1998	To provide specific policy concerning lubrication requirements of BFGAS. Servo Actuator products.		